

Using the Agilent U3401A Digital Multimeter


WARNING DO NOT CONNECT MORE THAN 2 WIRES TO METER

WARNING DO NOT ATTEMPT TO MEASURE VOLTAGE AND CURRENT AT SAME TIME

Measuring Resistance/Continuity

1. Press
2. Connect red and black leads as shown


Measure across device



Measuring Voltage

1. Press or
2. Connect red and black leads as shown

Power Supply Measure voltage in parallel




Measuring Current

1. Press or
2. Power off the measured circuit.
3. Connect red and black leads as shown.

Measure current in series

LESS THAN 0.5A



GREATER THAN 0.5A

